CALIFORNIA DEPARTMENT OF FORESTRY & FIRE PROTECTION OFFICE OF THE STATE FIRE MARSHAL

FIRE ENGINEERING - BUILDING MATERIALS LISTING PROGRAM

LISTING SERVICE

LISTING No. 7300-1214:101 Page 1 of 1

CATEGORY: Misc. Devices/Control Unit Accessories

LISTEE: Alarm-Saf, 65A Industrial Way, Wilmington, MA 01887-3499

Contact: *Michael Bone (978) 658-6717 Fax (978) 658-8638

DESIGN: Models AS/PBLP-12030-B03-UL, AS/PBLP-24025-B03-UL, AS/PBLN-12045-B03-UL and

AS/PBLN-24045-B03-UL power boosters. Refer to listee's data sheet (892-EP 52-102) for

detailed product description and operational considerations.

INSTALLATION: In accordance with listee's printed installation instructions, applicable codes and

ordinances and in a manner acceptable to the authority having jurisdiction.

MARKING: Listee's name, model number, electrical rating and UL label.

APPROVAL: Listed as control unit accessories for use with separately listed compatible control units.

Authority having jurisdiction should be consulted prior to installation.

NOTE: If the power booster goes into TOTAL FAILURE (No AC and no back up battery), the panel

> will be connected to the loop through the unit. For Typical Class B (Style Z) "Translator" Connection (12V panel to 24V indicators), the indicators will not function under this condition. As a safety measure, wire the trouble output contacts to a trouble indicating

device for annunciation of this and other fault conditions.

*Rev. 06-23-2004



This listing is based upon technical data submitted by the applicant. CSFM Fire Engineering staff has reviewed the test results and/or other data but does not make an independent verification of any claims. This listing is not an endorsement or recommendation of the item listed. This listing should not be used to verify correct operational requirements or installation criteria. Refer to listee's data sheet, installation instructions and/or other suitable information sources.

JUNE 23, 2004 Date Issued: Listing Expires June 30, 2005

DIANE K. AREND, Senior Deputy Authorized By:

Program Manager